



$P=f(Q_{vm})$



# SCHEMA



FAN	MOTOR	Phase	A	B	Fixing	
					D	Screw
S0300 COMP	TG30W04	3	116	154	360	M6
	MG30W04	1				
S0350 COMP	TG30W04	3	116	154	422	M6
	MG30W04	1				
S0400 COMP	TG50W04	3	136	174	470	M8
	MG50W04	1				
S0450 COMP	TG60W04	3	146	184	530	M8
	MG60W04	1				

